


Deformation measurement report No. 1

Date 21.06.2022


inspection date	Inspection mode	Start manhole	End manhole	Reach length
21.06.2022		START MH	FINISH MH	62.23m
Street	City	Material	Profile type	Profile type DN
Example Street	SUBURB	HDPE	C	C/450
Client name	Contractor present	Flow direction	Reach number	Build year
Cleanaway - Gold Coast Water	Drain Tech Australia		PIPE ID	0

Horizontal run



Horizontal average: 6.9%

Vertical run



Vertical average: -6.8%